

## Cab-Guard Out-Of-Service Guide



Color	Deficiency	Result
	No Cracks Allowed	Immediate Out of Service
	0 to 2 cm Cracks	Observe and Repair
	+2 cm Cracks	Immediate Out of Service
	0 to 3 cm Cracks	Observe and Repair
	+3 cm Cracks	Immediate Out of Service
All Weld Repairs Must Be Performed By a Certified/Ticketed Welder		

AMLCGOOS.indd June 5, 2015